

FocusAP Automation Series

FAC Auto Pickup and Loading Equipment




Features


- Automatic spread-out for FACs
- Precise pick-up and transfer
- Identification of the jig number and characters
- Protection functions


Applications


 Automatic pickup and loading

Product Dimensions (mm)









Remark: The structure drawing is for reference only. Please feel free to contact us for any special requirements.



Product Specifications

| Pr | o | tu | ct | Co | de |
|----|---|----|----|----|----|
| | | | | | |

Part No. FL-AP-LOAD-FAC

| General Data | Unit | Value |
|-------------------------------------|------|-------------------|
| Dimensions (Width x Depth x Height) | mm | 1100 x 800 x 2200 |
| Weight | kg | < 800 |

Testing Parameters

Cycle Time s/pcs TT = 3.5

Testing Ability Jig Quantity pcs/tray Loading Percent of Pass ≥ 99% Down Rate ≤ 1% Change Line Time min ≤ 15 Visual Resolution mm 0.053 (Pickup) / 0.02 (Positioning) Speed of Movement mm/s 1000

Software

Positioning Accuracy

System Software Identifies the jig number and characters, saves to the database, generates final tracking reports

mm

Communication Interface

Computer Interface GPIB USB2.0 RS232

Electric Parameter

Power Supply AC 220V / 50Hz

Protection

Alarming Protection

Sound and light alarm, security management, leakage protection, maintenance reminder, emergency stop, and more

 ± 0.025